



**SAFETY SYSTEM®**  
YOUR PROTECTOR

**Sir Safety System S.p.A. Single-member company**  
Wholly-owned subsidiary of Sir Holding Srl  
Via dei Fornaciai, 9 - Santa Maria degli Angeli  
06081 Assisi - Perugia - Italy  
Tel.+39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548  
Viale Europa 74  
20090 Cusago Milano  
Tel. +39 02.90394575  
Fax +39 02.90394441

**TECHNICAL SHEET**

**export@sirsafety.com**  
**www.sirsafety.com**

Quality Management  
System Certificate  
UNI EN ISO 9001:2015

|                                    |                       |   |
|------------------------------------|-----------------------|---|
| <b>Name: OXFORD GLAMOUR JACKET</b> | <b>Code: MC4012H1</b> | <b>MC40 HIGH VISIBILITY CLOTHING - RAINWEAR</b> |
|------------------------------------|-----------------------|---|

**Description**

High visibility jacket in 100% heat-sealed PU coated polyester. With concealed zipper closure, foldaway hood with drawstring, waterproof pockets with flap, elasticated windproof cuffs and covered ventilation mesh on the shoulders.

The product has been designed and manufactured to comply with Regulation (EU) 2016/425 and subsequent amendments.

EN ISO 20471

Class 3:



- 0.80 m fluorescent material;

- 0.20 m reflective material.

certified



|                              |  |   |
|------------------------------|--|---|
| <b>Category</b><br><b>II</b> | <b>Colours</b><br><b>HI-VIS ORANGE</b> | <b>Available Sizes</b><br><b>S - 3X</b> |
|------------------------------|--|---|

|   |   |  |
|---|---|--|
| <b>Quantity/Carton</b><br><br><br><br><br><br><br><br><br><br><b>10</b> | <b>EC Standards</b><br><b>EN 343</b><br> Water Resistance:3<br>Water Vapour Resistance:1 | <b>Important Information</b><br>General and Road Construction, Transport, Logistics, Industrial Plants Maintenance and Installation, Emergency Response Companies.<br><br>The performances of the garment are guaranteed when it is correctly worn and fastened.<br><br>Keep in a cool dry place, far from heat sources and direct light.<br>Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it.<br><br>We recommend to follow the washing instructions. |
|   | <b>EN ISO 20471</b><br> Class:3  |  |
| <b>Dexterity</b>  |   |  |