

06081 Assisi - Perugia - Italy

**TECHNICAL SHEET** 

export@sirsafety.com www.sirsafety.com





Name: MOTORWAY SPLIT JACKET

Sir Safety System S.p.A. Single-member company

Wholly-owned subsidiary of Sir Holding Srl

Via dei Fornaciai, 9 - Santa Maria degli Angeli

Tel.+39 075.8043737 - Fax +39 075.8048686

Code: MC4124E1

VAT Nr. IT 03359340548

20090 Cusago Milano

Tel. +39 02.90394575

Fax +39 02.90394441

Viale Europa 74

## MC41 HIGH VISIBILITY CLOTHING - WEATHER RESISTANT

## Description

Four-in-one high visibility pilot jacket in PU coated polyester and inner padding 220 g/m; the outer jacket is featuring a concealed central zipper closure, foldaway hood with drawstring, mobile phone pocket on the right with flap and Velcro fastening, side pockets with flap and Velcro, chest pocket with flap, detachable badge holder with snap button, vertical inner pocket and detachable inner jacket and sleeves.

Inner jacket detachable by zipper and snap buttons, in hi-vis colour: fleece collar, detachable sleeves, outer pockets with concealed zipper closure, two inner pockets, which one is featuring a zipper closure and the other one a mobile phone holder with flap and Velcro fastening.

The product has been designed and manufactured to comply with Regulation (EU) 2016/425 and subsequent amendments.

EN ISO 20471 Class 3: - Á0.80 m fluorescent material; - Á0.20 m reflective material.

V@AÚÒSUË/ÒÝí Á&∧¦cãa&æe∿Aį́Aô@Aį́æajĄ́ĭč∿¦Áæà¦a&ÁárÁ	OEKO-TEX® COMPODINCE IN TEXTILES STANDARD 100	
under review.		

Category	Colours	Available Sizes
II	HI-VIS YELLOW	S - S, 6X
Quantity/Carton	EC Standards EN 343 Water Resistance:3 Water Vapour Resistance:1	Important Information General and Road Construction, Road sign work, Road and plants maintenance, Service and assistance companies, Emergency response
5	EN 14058 Rct:3 AP:3 EN ISO 20471 Class:3	companies. Keep in a cool dry place, far from heat sources and direct light. Make sure the garment is in good condition, undamagedand clean before use. Once you become aware of a damage, you should immediately replace it.
		We recommend to follow the washing instructions.
Dexterity		Storage and cleaning